

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
	:	Examiner: Saeid E. Dehkordy
AKIHIKO NODA)	
	:	Group Art Unit: 2626
Appl. No.: 09/557,913)	
	:	Confirmation No.: 9394
Filed: April 21, 2000)	
	:	
For: PRINT CONTROL APPARATUS AND)	
P0RINT CONTROL METHOD CAPABLE OF	:	
CANCELING PRINT JOB)	
	:	
Patent No.: US 7,050,186 B1)	
	:	
Issued: May 23, 2006)	January 10, 2008

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050) is enclosed.

The \$100.00 fee for the Certificate of Correction is being paid electronically. However, the Commissioner is authorized to charge any underpayment or credit any overpayment to Deposit Account No. 06-1205.

Patentee's undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

/Mark A. Williamson/

Mark A. Williamson
Attorney for Patentee
Registration No. 33,628

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

MAW:eyw

Staple
Here
Only!

PRINTERS TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 7,050,186 B1

DATED : May 23, 2006

INVENTOR(S) : NODA

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET NO. 9 of 20:

Figure 10, "[PROPERTY]" should read--[PROPERTY]--.

COLUMN 2:

Line 49, "control" should read --controlling--.

Line 67, "control" should read --controlling--.

COLUMN 5:

Line 48, "temporarily" should read --temporarily stores--.

COLUMN 7:

Line 20, "has" should read --have--.

Line 43, "forth" should read --fourth--.

Line 52, "causes" should read --is caused--.

COLUMN 8:

Line 1, "causes" should read --is caused--.

COLUMN 13:

Line 47, "forth" should read --fourth--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,050,186 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 7,050,186 B1

DATED : May 23, 2006

INVENTOR(S) : NODA

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14:

Line 11, "corresponds" should read --correspond--.

Line 12, "is" should read --are--.

Line 26, "moved" should read --moves--.

Line 37, "recovers" should read --and recovers--.

Line 39, "direction." should read --directions.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,050,186 B1

No. of add'l. copies
@ 30¢ per page

